



दि न्यू इंडिया एश्योरन्स कंपनी लिमिटेड
(भारत सरकार का उपक्रम)
सूरत क्षेत्रीय कार्यालय (230000)
THE NEW INDIA ASSURANCE COMPANY LTD.
(Government of India Undertaking)
SURAT REGIONAL OFFICE (230000)



पहली मंज़िल, "ए विंग", तिरुपति
प्लाज़ा, बहुमाली बिल्डिंग के नज़दीक,
अठवागेट, सूरत, 395001

1st Floor, "A-Wing", Tirupati
Plaza, Near Family Court,
Athwagate, Surat - 395001

Website: www.newindia.co.in
E-mail: nia.230000@newindia.co.in
■ 0261- 2461589 / 2461690, 2460691, 2461582
CIN: L66000 MH1919 GOI 000526

Date: 23/09/2024

TENDER NO. : SRO/ESTB./SIGN/BOARD/PROCUREMENT/CUM/INSTALLATION/230000

TENDER NOTICE

The New India Assurance Co. Ltd. intends to invite the tender from the eligible vendors in a Single Bid system for the procurement cum installation of new Sign Board at our office namely Surat Regional Office (230000) as well as uninstalation of existing sign board.

Tender documents can be downloaded from the Company's website www.newindia.co.in.

Vendors can submit their Bids on or before 04/10/2024 up to 05:30 pm in a sealed envelope Super-scribed as "Quotation for the procurement cum installation of Sign Board" in the tender box after getting it in-warded in the register of the Surat RO (230000). The address of the office is as - Estate and Establishment department, C/O The New India Assurance Co. Ltd., Surat Regional Office, 1st Floor, A-Wing, Tirupati Plaza, Athwagate, Surat, 395001.

REQUIREMENT				
Sr. No.	Description	Qty	Dimension (in ft.)	*Rate
1.	Water-Resistance Polyvinyl Chloride coated thick flex which can withstand exposure to UV radiations and other environment factors compared to regular thin flex in market, provided with display matter printed display using ultraviolet special ink formulated to dry quickly & more durable, weather resistant and scratch resistant compared to regular ink in market. Further fixed on zinc coated galvanized iron hollow section welded frame	1	20×3	
2.	Buyback of existing sign board - Vendor has to uninstall the existing sign board and dispose of the same	1	20×3	

*Quoted Price should be exclusive of taxes.


The bidder should have a minimum experience of 3years in doing similar type of jobs. The Bidder cannot contract the job to the other person. Deviation from these two terms will render the bid rejected.

Bidders are requested to visit the site/office to have a better picture of the work that needs to be done.

Two or more bids from the same vendor will be rejected.

The New India Assurance Co. Ltd does not bind itself to accept any or all the bids and reserves the right to reject any or all bids without assigning any reason.

All updates, corrigendum, addendum etc. will be published on www.newindia.co.in only.


Mrs/ Bindu Jadav
Regional Manager
Surat Regional Office (230000)



बिन्दु जादव
क्षेत्रीय प्रबंधक
सूरत क्षेत्रीय कार्यालय (230000)
BINDU JADAV
REGIONAL MANAGER
SURAT REGIONAL OFFICE (230000)

२३/०९/२४